10e – Lightwood Road, Marsh Lane Bus Shelter



The roof of this older shelter is in a very poor state with holes in what appears to be an concrete/asbestos ridged panel roof, the shelter and boarding point also fail to meet latest accessibility standards.